॥ ಶ್ರೀ ಗಂಗಮ್ಮ ಕೃಪಾ ॥

ಸಮೃದ್ಧಿ

Smt. Kavitha Singh
Mo. 9964702826

Samrudhi Ground Water Consultant

46, Gangamma Temple Street, Near Gangamma Temple, Malleswaram, Bangaloare-03

Ref. :..... Date : .....

REPORT ON GROUND WATER INVESTIGATION

Name Drilling borewell (3"0)

Address Pagandlli village

Location

Topography 6½" dia - drilling

Soil Type

Rock Type

RECOMMENDATIONS

Nos.

Depth		Depth	
Casing	180 Feet	Casing	
Yield	900 Feet	Yield	
Aquifers		Aquifers	

Remarks

Note : The Survey was carried out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ, ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it... ಗಿಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ

Smt. Kavitha Singh

Water Diviner

ಸಮೃದ್ಧಿ

॥ ಶ್ರೀ ಗಂಗಮ್ಮ ಕೃಪಾ ॥

Smt. Kavitha Singh
Mo. 9964702826

Samrudhi Ground Water Consultant

46, Gangamma Temple Street, Near Gangamma Temple, Malleswaram, Bangaloare-03

Yadagiri

6 1/2 Inch Bore drilled

Nagandli village

Yield Thirty Feet Yield

Borewell at end drilling is

failure

Note : The Survey was carried out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

Smt. Kavitha Singh

Water Diviner